



<p>Repair Code "A"</p> <p>The sidewalk is cracked with a vertical edge of more than one inch high. This may be a one – or two-panel replacement.</p>	
<p>Repair Code "B"</p> <p>The sidewalk has raised and has caused more than two (2") inches of horizontal separation between panels or a slope of more than 5% on either panel above grade of adjacent panels.</p>	
<p>Repair Code "C"</p> <p>The sidewalk is depressed and has caused more than two (2") inches of horizontal separation between panels or a slope of more than 5% on either panel above grade of adjacent panels.</p>	
<p>Repair Code "D"</p> <p>The sidewalk has cracked into four or more pieces per 4'x4' square AND sections are distorted or distressed with a vertical height difference of one-half ($\frac{1}{2}$") inch or more or a horizontal separation of two (2") inches or more.</p>	
<p>Repair Code "E"</p> <p>The sidewalk has cracked and part of the sidewalk is missing, forming holes. Note panel for futher inspection by Engineer.</p>	
<p>Repair Code "F"</p> <p>The sidewalk has settled or for some other reason sloped and tilted more than one (1") inch per foot or 8% toward either side.</p>	
<p>Repair Code "G"</p> <p>More than half of the panel has spalled AND there is a one-half ($\frac{1}{2}$") inch or more vertical depression caused by the spalling.</p>	